


TEXAS UTILITIES GENERATING COMPANY
SKYWAY TOWER - 400 NORTH OLIVE STREET, L.B. 81 - DALLAS, TEXAS 75201

October 15, 1986

WILLIAM G. COUNCIL
EXECUTIVE VICE PRESIDENT



Mr. Eric H. Johnson, Director
Division of Reactor Safety and Projects
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NO. 50-446
UNCONSOLIDATED CONCRETE - UNIT 2 RCB EXTERIOR WALL
SDAR: CP-86-65 (INTERIM REPORT)

Dear Mr. Johnson:

On September 15, 1986, we verbally notified your Mr. I. Barnes of a deficiency involving unconsolidated concrete in the exterior wall of CPSES Unit 2 Reactor Containment Building. This is an interim report of a potentially reportable item under the provision of 10CFR50.55(e).

The condition was identified during the performance of a concrete surface repair which requires chipping of the affected area to sound concrete. Due to the extent of chipping required to reach sound concrete, an evaluation is underway to determine the possible adverse affects of the concrete void.

We anticipate completing our evaluation by November 21, 1986. Our next report on this issue will be submitted by December 17, 1986.

Very truly yours,

A handwritten signature in cursive script that reads "W. G. Council".

W. G. Council

JCH/mTh

c - NRC Region IV (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8610230064 861015
PDR ADOCK 05000446
S PDR

86-1184

10 IE-27