. 330131 01:06



JUL 2 B 1986

L-86-315

Dr. J. Nelson Grace Regional Administrator, Region II U. S. Nuclear Regulatory Commission 101 Marietta Street N.W., Suite 2900 Atlanta, Georgia 30323

Re: Turkey Point Units 3 and 4 Docket Nos 50-250 and 50-251

IE Bulletin 86-02

Dear Dr. Grace:

We have reviewed IE Bulletin 86-02 (Static "O" Ring Differential Pressure Switches) as it applies to Turkey Point Units 3 and 4. We have performed an inspection to determine the extent to which SOR Series 102 and 103 differential pressure switches are installed at Turkey Point. The search has indicated that SOR series 102 or 103 differential pressure switches are not used in safety related or quality related (important to safety) applications at Turkey Point.

Should you or your staff have any questions on this information, please contact us.

Very truly yours,

C. O. Woody Group Vice President

Nuclear Energy

COW/SAV:jss

cc: Harold F. Reis, Esquire

USNRC Document Control Desk

8610240421 860728 PDR ADOCK 05000250 Q PDR TED PEOPLE ... SERVING PEOPLE

STATE OF FLORIDA )

COUNTY OF DADE )

C. O. Woody, being first duly sworn, deposes and says:

That he is a Group Vice President of Florida Power & Light Company, the licensee herein;

That he has executed the foregoing document; that the statements made in this document are true and correct to the best of his knowledge, information, and belief, and that he is authorized to execute the document on behalf of said Licensee.

C. O. Woody

Subscribed and sworn to before me this

28th day of July, 1986.

NOTARY PUBLIC, in and for the County of Dade, State of Florida.

My commission expires:

NOTARY PUBLIC STATE OF FLORTOA MY COMMISSION EXP. MAY 12,1990 BONDED THRU GENERAL INS. UND.