

MAY 7 1987

Docket No. 50-016
Docket No. 50-341

The Detroit Edison Company
ATTN: B. Ralph Sylvia
Group Vice President
Nuclear Operations
6400 North Dixie Highway
Newport, MI 48166

Gentlemen:

This refers to the routine safety inspection conducted by Mr. R. A. Paul of this office on April 6-10, 1987, of activities at Fermi, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-9 and No. NPF-33 and to the discussion of our findings with members of your staff at the conclusion of the inspection.


The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.


We will gladly discuss any questions you have concerning this inspection.

Sincerely,


W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch


Enclosure: Inspection Reports
No. 50-016/87001(DRSS)
No. 50-341/87018(DRSS)

See Attached Distribution

RIII

Paul Jaw


RIII

Greger

RIII

Greenfield
Jackson

70
RIII

Weil
5/7/87

RIII

Shafer

TEC 6
11

8705120300 870507
PDR ADOCK 05000016
Q PDR

MAY 7 1987

Distribution

cc w/enclosure:

F. H. Sondgeroth, Licensing
Engineer

P. A. Marquardt, Corporate
Legal Department

DCS/RSB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Ronald Callen, Michigan

Public Service Commission

Harry H. Voight, Esq.

Michigan Department of

Public Health

Monroe County Office of

Civil Preparedness