

Point Beach Nuclear Plant 6610 Nuclear Rd., Two Rivers, Wi 54241 (414) 755-2321

TEQ2/

NPL 97-0436

10 CFR 50.73

July 30, 1997

Document Control Desk
U.S. NUCLEAR REGULATORY COMMISSION
Mail Station P1-137
Washington, D. C. 20555

Ladies/Gentlemen:

DOCKETS 50-266 AND 50-301 LICENSEE EVENT REPORT 97-033-00 NON-EXEMPT POWER CABLES DO NOT MEET APPENDIX R SEPARATION CRITERIA POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

Enclosed is Licensee Event Report 97-033-00 for Point Beach Nuclear Plant. Units i and 2. This report is provided in accordance with 10 CFR 50.73(a)(2)(ii)(B), "Any event or condition that resulted in the nuclear power plant being in a condition that was cutside the design basis of the plant." This report describes the discovery that redundant power cables in the auxiliary feedwater pump room do not meet the Appendix R separation criteria and have not been provided exemption from the requirement.

If you require additional information, please contact us.

Sincerely,

Douglas F. Johnson

Manager,

Regulatory Services & Licensing

Tought Zollen

Enclosure

ce: NRC Resident Inspector

NRC Regional Administrator

9708070197 970730 PDR ADOCK 05000266 S PDR