

**ATTACHMENT 2**

**QUAD CITIES NUCLEAR POWER STATION**

**UNIT 2**

**PLANNED MAINTENANCE**

**OUTAGE (Q2P02)**

**TECHNICAL SPECIFICATION 3/4.8.F SNUBBER FUNCTIONAL TESTING SCOPE**

**QUAD CITIES UNIT 2 TECH SPEC (SAFETY RELATED) SNUBBER POPULATION IS 129 SNUBBERS**

**A. FUNCTIONAL TESTING SCOPE**

**1. TECHNICAL SPECIFICATION 10% SAMPLE AND SERVICE LIFE MONITORING SAMPLE:**

a. Testing will be performed with the following procedures:

- QCAP 0410-05
- QCTS 0750-05

b. Breakdown of the sample is:


- 6 snubbers in the Drywell
- 6 snubbers in the Reactor Building
- 1 snubber in the Turbine Building


c. System breakdown of the 10% sample:

**Tech Spec Snubbers:**

TECH SPEC #	SYSTEM #	MM NWR#	SERIAL #	SNUBBER TYPE AND SIZE	ISI NUMBER	LOCATION	DRAWING NUMBER
2-032	0300	980031326-01	8515	PSA-1	NON-CODE	DRYWELL 1ST LEVEL	M-1053-BF SHT. 1 & 4
2-050	3000	980031932-01	7931	PSA-35	NON-CODE	TURBINE BLDG	M-1020D-1 SHT. 1,2,3
2-056*	3000	980031935-01	61300/63	LISEGA-5/10K	3001A-M-102.3	DRYWELL 2ND LEVEL	M-328E SHT. 3
2-065	3000	980032104-01	61308/49	LISEGA-4	NON-CODE	DRYWELL 1ST LEVEL	M-328F SHT. 15
2-072*	3000	980032105-01	61310/37	LISEGA-6	3001D-M-101.2	DRYWELL 2ND LEVEL	M-328H SHT. 2
2-083*	1000	980032379-01	16588	PSA-3	1025-M-102.1 A&B	DRYWELL 1ST LEVEL	M-1022D-8 SHT. 1,2,3
2-085*	1000	980032381-01	24460	PSA-3	1025-M-101 A&B	DRYWELL 1ST LEVEL	M-1022D-9 SHT. 1,2,3
2-093	1000	980032383-01	9254	PSA-35	NON-CODE	REACTOR BLDG BASEMENT	M-1802-13 SHT. 1,2,3
2-101	1000	980032106-01	779	PSA-100	NON-CODE	REACTOR BLDG BASEMENT	M-1802-05 SHT. 1,2
2-130*	1400	980032107-01	10394	PSA-10	1403-W-207 A&B	REACTOR BLDG (TOP OF TORUS)	M-1811-35 SHT. 1 & 2
2-135	1300	980032110-01	7748	PSA-10	NON-CODE	2B CORE SPRAY CORNER ROOM	M-1814-08 SHT. 1, & 2
2-137	1000	980032111-01	3299	PSA-1	NON-CODE	REACTOR BLDG (TOP OF TORUS)	M-1984
2-144*	1000	980032112-01	7717	PSA-10	1016C-M-201.1	2B RHR CORNER ROOM	M-1806-12 SHT. 1 & 2

Q2P02 SNUBBER TESTING SCOPE

 Date: 4-8-98  
Michael A. Bompeo  
Snubber Coordinator x2165 Pager# 354  
Engineering Programs Group

 Date: 4/8/98  
Gary Converse  
Snubber Coordinator Back-up x2179 Pager# 639  
Engineering Programs Group