



Point Beach Nuclear Plant  
6610 Nuclear Rd., Two Rivers, WI 54241

(920) 755-2321

NPL 98-0165

March 4, 1998

Document Control Desk  
U.S. NUCLEAR REGULATORY COMMISSION  
Mail Station P1-137  
Washington, D. C. 20555

Ladies/Gentlemen:

DOCKETS 50-266 AND 50-301  
LICENSEE EVENT REPORT 98-009-00  
INADEQUATE TECHNICAL SPECIFICATION SURVEILLANCE OF  
UNDervOLTAGE CONTACTS IN SAFEGUARDS SEQUENCE CIRCUITRY  
POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

Enclosed is Licensee Event Report 98-009-00 for Point Beach Nuclear Plant, Unit 1 and Unit 2. This report is provided in accordance with 10 CFR 50.73(a)(2)(i)(B), "Any operation or condition prohibited by the plant's Technical Specifications." This report describes the discovery of undervoltage relay contacts in the safeguards sequence circuitry that were not tested in accordance with the requirements of Technical Specification 15.4.6.A.2 and Table 15.4.1-1 Item 13.

New commitments established within this report are present in italics.

Please contact us if you require additional information.

Sincerely,

A handwritten signature in dark ink, appearing to read 'Douglas F. Johnson'.

Douglas F. Johnson  
Manager,  
Regulatory Services & Licensing

Enclosure

cc: NRC Resident Inspector  
NRC Regional Administrator  
NRC Project Manager

PSCW  
INPO Support Services

9603100226 980304  
PDR ADOCK 05000266  
S PDR

