Illinois Power Company Clinton Power Station P.O. Box 678 Clinton, IL. 61727 Tel. 217 935-5623 Fax. 217 935-4632

Walter G. MacFarland IV Senior Vice President and Chief Nuclear Officer

U-602991

April 29, 1998

Docket No. 50-461

An Illinova Company

Mr. A. Bill Beach Regional Administrator Region III U.S. Nuclear Regulatory Commission 801 War enville Road Lisle, Illinois 60532-4351

Subject:

ILLINOIS

Correction to Response to Notices of Violation Contained in Inspection Report 50-461/96009-01

Dear Mr. Beach:

In "Response to Notices of Violation Contained in Inspection Report 50-461/96009 (IP letter U-602725, dated April 9, 1997), a statement was made in Attachment 1 that Illinois Power is currently in full compliance with regards to restoration from bus outages per CPS 3509.01C001, "Division 1 NSPS Bus Outage Restoration Checklist." As noted in NRC Notice of Violation 50-461/97019-03, the procedure had not yet been revised at the time of that submittal. Subsequently, the revised CPS procedure 3509.01C001 was issued for use on October 30, 1997. Illinois Power's response to Notice of Violation 50-461/97019-03 committed to correcting the response to NOV 50-461/96009-01. This letter satisfies that commitment.

If you have any questions regarding this matter, please contact Joe V. Sipek, Director - Licensing at (217) 935-8881 extension 3405.

Sincerely yours,

Walter G. MacFarland, IV Senior Vice President and

Chief Nuclear Officer