



DEPARTMENT OF THE ARMY  
VICKSBURG DISTRICT, CORPS OF ENGINEERS

P. O. BOX 60

VICKSBURG, MISSISSIPPI 39160

REPLY TO  
ATTENTION OF:

CELMK-SO (385-11m)

22 Jun 87

87 JUL 2 P1:08

MEMORANDUM FOR: US NRC, Region II, 101 Marietta Street, NW,  
Atlanta, GA 30323

SUBJECT: Response to Notice of Violation, NRC Inspection Report,  
No. 23-01544-16/87-01

1. I concur with your finding that the Vicksburg District is in violation of our NRC License No. 23-01544-16 as it pertains to authorized permanent storage of our Troxler moisture/density gauges. This oversight occurred with our recent acquisition of additional gauges. It had been our initial intent to maintain these gauges at our Ruby, LA location. Sometime later the decision was made to place the gauges at other locations to facilitate their use throughout the District. Regrettably, this decision was not preceded by a request to amend our license accordingly. Such a request has now been prepared, and a copy of that request is attached.

2. With all other requirements of our license in order, I trust this will resolve the discrepancy noted in your survey. If you have any further questions please call me or my Safety and Occupational Health Manager, Mac Wimbish, at FTS 542-5095.

PAT M. STEVENS IV  
Colonel, Corps of Engineers  
Commander

CF:  
CEEC-SI

8707130191 870622  
REG2 LIC30  
23-01544-16 PDR

11  
IEC1



DEPARTMENT OF THE ARMY  
VICKSBURG DISTRICT, CORPS OF ENGINEERS

P. O. BOX 60  
VICKSBURG, MISSISSIPPI 39180

REPLY TO  
ATTENTION OF:

CELMK-SO (385-11m)

22 Jun 87

MEMORANDUM FOR: US NRC, Region II, 101 Marietta Street, NW,  
Atlanta, GA 30323

SUBJECT: Response to Notice of Violation, NRC Inspection Report,  
No. 23-01544-16/87-01

1. I concur with your finding that the Vicksburg District is in violation of our NRC License No. 23-01544-16 as it pertains to authorized permanent storage of our Troxler moisture/density gauges. This oversight occurred with our recent acquisition of additional gauges. It had been our initial intent to maintain these gauges at our Ruby, LA location. Sometime later the decision was made to place the gauges at other locations to facilitate their use throughout the District. Regrettably, this decision was not preceded by a request to amend our license accordingly. Such a request has now been prepared, and a copy of that request is attached.

2. With all other requirements of our license in order, I trust this will resolve the discrepancy noted in your survey. If you have any further questions please call me or my Safety and Occupational Health Manager, Mac Wimbish, at FTS 542-5095.

PAT M. STEVENS IV  
Colonel, Corps of Engineers  
Commander

CF:  
CEEC-SI