



SACRAMENTO MUNICIPAL UTILITY DISTRICT 6201 S Street, P.O. Box 15830, Sacramento CA 95852-1830, (916) 452-3211
AN ELECTRIC SYSTEM SERVING THE HEART OF CALIFORNIA

GCA 87-254

JUN 30 1987

J. B. Martin, Regional Administrator
U.S. Nuclear Regulatory Commission
Region V, Office of Inspection & Enforcement
1450 Maria Lane, Suite 210
Walnut Creek, CA 94596

Docket No. 50-312
Rancho Seco Nuclear Generating Station
License No. DPR-54
SPECIAL REPORT NO. 87-11: FIRE SUPPRESSION AND DETECTION SYSTEMS
INOPERABLE IN ZONE 32

Dear Mr. Martin:

The Sacramento Municipal Utility District hereby submits Special Report No. 87-11 in accordance with Technical Specifications, Section 3.14 and 6.9.5.E.

During Cold Shutdown conditions on May 18, 1987, at 10:05 P.M., Fire Zone 32 Detection and Water Spray Subsystems were placed under clearance (i.e., tagged out) due to reoccurring audible alarms and trouble signals on panel H3FPA. Fire Zone 32 covers the Turbine Building Main Lubricating Oil Area on the grade level.

Work Request No. 130429 was issued to troubleshoot and repair the subsystems. The subsystems listed above are scheduled to be returned to service before September 1, 1987. In the meantime, the compensatory measure, to establish fire watches, is being performed per Section 3.14.3.2 of the Technical Specifications for the above-listed fire zone.

8707150443 870630
PDR ADOCK 05000312
S PDR


RECEIVED
MRC
1987 JUL -1 P 2:04
REGION V

IE 2 1/10

J. B. Martin
GCA 87-254
Page 2

If there are any questions concerning this report, please contact
Mr. Ron W. Colombo at (916) 452-3211, extension 4236.

Sincerely,


G. Carl Andognini
Chief Executive Officer, Nuclear

Attachment

cc: A. D'Angelo
G. Kalman
INPO