



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

MAR 06 1989

Docket No. 50-341

The Detroit Edison Company
ATTN: B. Ralph Sylvia
Senior Vice President
Nuclear Operations
6400 North Dixie Highway
Newport, MI 48166

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. W. G. Rogers, S. Stasek and K. Ridgway of this office on January 1 to February 17, 1989, of activities at Fermi 2 authorized by Facility Operating License No. NPF-43 and to the discussion of our findings with Mr. B. Sylvia at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Richard C. Knop, Chief
Reactor Projects Branch 3

Enclosures:

1. Notice of Violation
2. Inspection Report
No. 50-341/89002(DRP)

See Attached Distribution

IEO1
11

Distribution

cc w/enclosures:

Patricia Anthony, Licensing

P. A. Marquardt, Corporate

Legal Department

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Ronald Callen, Michigan

Public Service Commission

Harry H. Voight, Esq.

Michigan Department of

Public Health

Monroe County Office of

Civil Preparedness