



Log # TXX-6918
File # 10110
908.3
Ref # 10CFR50.55(e)

November 6, 1987

William G. Council
Executive Vice President

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION
DOCKET NOS. 50-445 AND 50-446
SEPARATION BARRIER MATERIAL ON POWER CABLES AND
POWER RACEWAYS
SDAR: CP-86-83 (INTERIM REPORT)

Gentlemen:

On June 5, 1987, we notified you by our letter logged TXX-6840 of a deficiency involving the use of Separation Barrier Material (SBM) on power cables and power raceways which we deemed reportable under the provisions of 10CFR50.55(e). This is an interim report submitted to status corrective actions implemented to date. Our latest interim report was logged TXX-6690, dated August 28, 1987.

Our effort to define the construction schedule for this issue is continuing. We will submit the next report no later than January 18, 1988.

Very truly yours,

W.G. Council

W. G. Council

By:

D.R. Woodlan

D. R. Woodlan

Supervisor, Docket Licensing

WJH:tgj

c-Mr. R. D. Martin, Region IV
Resident Inspectors, CPSES (3)

8711130345 871106
PDR ADOCK 05000445
S PDR

TE27
1/0