SAFETY INSPECTION

DMB COPY

1. LICENSEE

CONSULTING RADIOLOGISTS CORP. 421 MICHIBAN ST. TOLEDO, OH 43624

2. REGIONAL OFFICE U.S. NUCLEAR REGULATORY COMMISSION

REGION III 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137

4. LICENSE NUMBER(S)

5. DATE OF INSPECTION

03012880

34-17518-01

8-10-87

was not properly posted to indicate the presence

Licensee

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commissions (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

1. Within the scope of this inspection, no violations were observed.

2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.

3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements. THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11.

	of a	. 10 CFR 20.203(b), (c), (d), (e) or 34.4:
]В.	Containers located in	were not properl
_	labeled to indicate the presence of radioactive material. 1	10 CFR 20.203(f)(1), or (f)(2).
7c.		of sealed sources were not performed at the proper
		License Condition Number
7 D.	Records of	were not properly maintained
		or License Condition Number
100	risports or ristributions or	were not made in accordance
,	with 10 CFR	
_	with 10 CFR	or License Condition Number
] H.	with 10 CFR	or License Condition Number
] H.	with 10 CFR	or License Condition Number

hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC