



TUELECTRIC

Log # TXX-6694
File # 10110
903.8
Ref # 10CFR50.55(e)

William G. Counsil
Executive Vice President

August 31, 1987

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NO. 50-445
LINER ATTACHMENT MATERIAL REQUIREMENTS: IMPACT TESTING
SDAR: CP-87-22 (INTERIM REPORT)

Gentlemen:

On June 17, 1987, we verbally notified your Mr. Shannon Phillips of a deficiency wherein FSAR and specification requirements regarding impact testing of materials attached to the containment liner have not been implemented. This is an interim report of a potentially reportable item under the provisions of 10CFR50.55(e). Our latest interim report, logged TXX-6579, was submitted on July 17, 1987.

Engineering is currently performing a fracture mechanics analysis to evaluate the effect of the non-impact tested material on the liner. Upon completion of this analysis we will determine any safety significance and reportability pursuant to 10CFR50.55(e).

We will provide our next report by October 26, 1987.

Very truly yours,

W. G. Counsil

By:
G. S. Keeley
Manager, Nuclear Licensing

BSD/amb

c - Mr. R. D. Martin, Region IV
Resident Inspectors, CPSES (3)

8709040015 870831
PDR ADDCK 05000445
S PDR

IE27
1/0