SIGNATURE - LICENSEE

SAFETY INSPECTION

DAB COPY

		one copy
MADISON METROPOLITAN SEWERAGE DISTRICT 1610 MOORLAND ROAD MADISON, WI 53713		U.S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE OF INSPECTION
03011309	48-16604-01	8/11/87
Licensee:		
Regulatory Commission's (NRC) rules an and representative records, interviews, w	d regulations and the conditions of you ith personnel, and observations by the	se as they relate to radiation safety and to compliance with the Nuclear or license. The inspection consisted of selective examinations of procedures inspector. The findings as a result of this inspection are as follows:
1. Within the scope of this inspection	n, no violations were observed.	
The inspector also verified the ste those actions at this time.	ps you have taken to correct the violati	ions identified during the last inspection. We have no further questions on
3. During this inspection pertain of y	your activities, as checked below, were	in violation of NRC requirements.
	ION which is required to be posted in a	
		was not properly posted to indicate the presence
		. 10 CFR 20.203(b), (c), (d), (e) or 34.42.
B. Containers located in		were not properly
labeled to indicate the presenc	e of radioactive material. 10 CFR 20.2	03(t)(1), or (t)(2).
Пс		of sealed sources were not performed at the propec-
frequencies, 10 CFR		License Condition Number
Company of		was not properly maintained
		were not properly maintained.
E. Documents were not properly	posted or otherwise made available. 10) CFR 19.11.
F Reports or notifications of		were not made in accordance
with 10 CFR		r License Condition Number
L J H.	AND THE RESIDENCE AND ADDRESS OF THE RESIDENCE OF THE PROPERTY OF THE PARTY OF THE	
J		
	V 2.2004.2.1.100.100.100.100.100.100.100.100.100	
L. K.	acasaning a signatural dang ini ana asalah kataran kelebih kelapan dan kelebih kelebih kelebih dan kelebih dan kelebih	
This statement of corrective actions is ma	tions described by me to the inspector of the inspector o	will be taken to correct the violations identified in the items checked above, is of 10 CFR 2,201. No further response will be submitted unless required by
the NRC.		
8708200266 870811 REG3 LIC30		Rose on Partrat 18/11/8-
48-16604-01 PDF		Bose on tankrat 18/11/87

IE070/1