

JUN 06 1989

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Donald Shelton
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by Mr. T. Ploski of this office on May 15-19, 1989 of activities at the Davis-Besse Nuclear Power Station, Unit 1, authorized by NRC Operating License No. NPF-3, and to the discussion of our findings with Mr. B. DeMaison and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

L. Robert Greger
L. Robert Greger, Chief
Reactor Programs Branch

Enclosure: Inspection Report
No. 50-346/89013 (DRSS)

See Attached Distribution

yes
RIII
wls
Ploski/cg
ja

yes
RIII
wls
Snell
6/6/89

(initials)
RIII
RD
DeFayette
6/6/89

RIII
(initials)
Greger
6/6

IE 35
11

Distribution

cc w/enclosure:

L. Storz, Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Harold W. Kohn, Ohio EPA

James W. Harris, State of Ohio

Roger Suppes, Ohio

Department of Health

State of Ohio, Public

Utilities Commission

W. Travers, EPB, NRR

J. Foster, RIII

R. Landsman, RIII

D. Bement, FEMA, RV