## SAFETY INSPECTION

1. LICENSEE 2 REGIONAL OFFICE ST. JOSEPH'S MEDICAL CENTER U.S. NUCLEAR REGULATORY COMMISSION 801 E. LASALLE ST. REGION III 799 ROOSEVELT RD. SOUTH BEWD, I NOIANA 46634 GLEN ELLYN, IL 60137 3. DOCKET NUMBER(S) 5. DATE OF INSPECTION 13-02650-02 JUNE 16,1989 030-13685 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commissions (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows: 1. Within the scope of this inspection, no violations were observed. 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time. 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements. THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11. was not properly posted to indicate the presence ofa \_\_\_. 10 CFR 20.203(b), (c), (d), (e) or 34.42. B. Containers located in \_\_\_ were not properly labeled to indicate the presence of radioactive material. 10 CFR 20,203(f)(1), or (f)(2), of sealed sources were not performed at the proper License Condition Number \_ frequencies. 10 CFR D. Records of \_\_\_\_\_ were not properly maintained. 10 CFR or License Condition Number E. Documents were not properly posted or otherwise made available. 10 CFR 19.11. F. Reports or notifications of \_\_\_\_ were not made in accordance or License Condition Number with 10 CFR 8908140365 890616 PNU I hereby state that within 30 days the actions described by morto the impector will be taken to correct the violations identified in the items checked above. This gratement of corrective actions is made in accordance with the requirements of 10 EFR 2.201. No further response will be submitted unless required by