Dr. Lawrence Ruby, Director Reactor Facility Reed College 3203 SE Woodstock Blvd. Portland, Oregon 97202

Dear Dr. Ruby:

SUBJECT: REACTOR OPERATOR REQUALIFICATION PROGRAM FOR THE REED COLLEGE

REACTOR FACILITY

The operator requalification program that you submitted on July 5, 1989 has been reviewed and additional information is requested. Enclosed is the "Request for Additional Information." If you have any questions, please call me at (301) 492-1102.

Sincerely,

Theodore S. Michaels, Project Manager Non-Power Reactor, Decommissioning and Environmental Project Directorate Division of Reactor Projects III, IV.

V and Special Projects Office of Nuclear Reactor Regulation

Enclosure: As stated

cc: See next page

DISTRIBUTION:
Docket File
NRC & Local PDRs
PDSNP R/F
EHylton
TMichaels
EJordan
BGrimes
OGC-Rockville
ACRS (10)

OFOI

(LETTER RUBY)

PDNPADE EUDITON 08/1/89 PDNPRDE/ym TMichaels:cw 08//4/89 PDNPRDE SWe1ss 08/14/89

8908180105 890814 PDR ADOCK 05000288 PDC



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555 August 14, 1989

Docket No. 50-288

Dr. Lawrence Ruby, Director Reactor Facility Reed College 3203 SE Woodstock Blvd. Portland, Oregon 97202

Dear Dr. Ruby:

SUBJECT: REACTOR OPERATOR REQUALIFICATION PROGRAM FOR THE REED COLLEGE

REACTOR FACILITY

The operator requalification program that you submitted on July 5, 1989 has been reviewed and additional information is requested. Enclosed is the "Request for Additional Information." If you have any questions, please call me at (301) 492-1102.

Sincerely.

Theodore S. Michaels, Project Manager Non-Power Reactor, Decommissioning and Environmental Project Directorate

Division of Reactor Projects III, IV, V and Special Projects

Office of Nuclear Reactor Regulation

Enclosure: As stated

cc: See next page

cc: Director, Oregon Department
Of Energy
528 Cottage Street, N. E.
Salem, Oregon 97310

Mayor of City of Portland 1220 Southwest 5th Avenue Portland, Oregon 97204

Administrator
Siting and Regulation
Oregon Department of Energy
Labor and Industries Building
Room 111
Salem, Oregon 97310

REQUEST FOR ADDITIONAL INFORMATION
REED COLLEGE REACTOR FACILITY
OPERATOR REQUALIFICATION PROGRAM

BACKGROUND

By letter dated July 5, 1989, Reed College (the Licensee) requested that the staff review the licensee's operator requalification program. While the program meets the criteria of ANSI/ANS 15.4, "Selection and Training of Personnel for Research Reactors," it does not meet the criteria of 10 CFR 55.59, "Requalification." Our review and request for additional information follows.

SECTION 4

On-The-Job Training

The requirements of 10 CFR 55.59(c)(3)(i) state that the requalification program must consist of on-the-job training consisting of control manipulations applicable to the plant design. Licensee must clarify which of these manipulations specified in 10 CFR 55.59(c)(3)(i) are applicable to the facility and include this list of manipulations in the program description of operator on-the-job training.

SECTION 6

Evaluation

The requirements of 10 CFR 55.59(a)(2)(i) state that the annual written examination sample the items specified in 10 CFR 55.41 and 10 CFR 55.43 to the extent applicable to its facility. Furthermore, the requirements of 10 CFR 55.59(a)(2)(ii) state that operators and senior operators must be examined such that they demonstrate an understanding of the ability to perform the actions necessary to accomplish a comprehensive sample of items specified in 10 CFR 55.45(a)(2) through (13) inclusive to the extent applicable to the facility. Licensee must clarify which of these items are applicable to its facility and include this list of items to be included in the written and operating examination.