

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

June 20, 1989


U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Attention: Document Control Desk

Subject: McGuire Nuclear Station
Docket Numbers 50-369 and -370
Semi-Annual Effluent Release Report
Revisions

Inspection Report 50-369, 370/89-12 identified a violation, "Failure to Include A Description of Unplanned Releases In the Semi-Annual Effluent Release Report." Attached please find letters dated August 31, 1987 and February 29, 1988, which originally transmitted these reports for the 1988 calendar year. Each has been provided with a supplemental attachment which describes the identified release. In addition, a transcription error in the February 29, 1988 report, which incorrectly quantifies the abnormal release has been corrected.

Very truly yours,



H. B. Tucker

SAG173/lcs

xc: Mr. S. D. Ebnetter
Regional Administrator, RII
U. S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, Georgia 30323

Mr. Darl Hood
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. P. K. VanDoorn
Sr. NRC Resident Inspector
McGuire Nuclear Station

8907070141 890620
PDR ADDCK 05000369
Q PNU

IE48
1/1

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

August 31, 1987

Dr. J. Nelson Grace, Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
101 Marietta St. NW, Suite 2900
Atlanta, Georgia 30323

Subject: McGuire Nuclear Station
Docket Nos. 50-369 and 50-370
Semi-Annual Effluent Release Report


Dear Dr. Grace:

Pursuant to McGuire Nuclear Station's Technical Specifications, attached is the station's Semi-Annual Effluent Release Report (SERR), covering the period January 1, 1987 through June 30, 1987. Attachment I provides a summary of liquid and gaseous effluent releases, as well as solid wastes shipped offsite. Also, a list of instrumentation which was inoperable during the period is provided.

As a result of radiation releases from McGuire Nuclear Station, no member of the public received an annual calculated dose exceeding those set forth in 40 CFR Part 190. This determination was made considering that there are no other fuel cycle facilities nearby which would significantly increase the dose to any member of the public.

A revision to McGuire's Offsite Dose Calculation Manual (ODCM) was submitted during the first half of 1987. (Reference: H.B. Tucker to H.R. Denton, January 6, 1987) No revisions to McGuire's Process Control Program (PCP) were made in this period. Technical Specifications require that revisions to both the PCP and ODCM be reported in the SERR.

Very truly yours,



Hal B. Tucker

SAG/83/jgc

Attachment

~~8709290439~~ 3pp

Dr. J. Nelson Grace

August 31, 1987

Page 2

cc: w/attachment

Mr. Harold Denton, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. W.T. Orders
NRC Resident Inspector
McGuire Nuclear Station

Dr. J. Nelson Grace
August 31, 1987
Page 3

bxc: H.J. Dameron
J.W. Foster
N.A. Rutherford
R.L. Gill
MC-801.02
MC-818.02
(6)