

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

August 8, 1989

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: McGuire Nuclear Station  
Docket Nos. 59-369, 370  
Inspection Report Nos. 369, 379/89-05  
Notice of Corrective Action Delay

Gentlemen:

In your June 23, 1989 letter you requested a revised response to violation 369, 370/89-05.


We agreed to submit a revised response addressing our management initiatives in the area of procedural compliance by August 5, 1989.

Due to the extensive review of station procedures that is required, this process is not yet complete.

Station management is continuing to review procedures in order to formulate a program which will resolve this concern.

Full compliance for these corrective measures will be completed no later than August 18, 1989.

Very truly yours,



H. B. Tucker

WTB84/lcs

8908230231 890808  
PDR ADOCK 05000369  
Q PDC

JE01  
1/0