

JUL 6 1989

Marymount Hospital
ATTN: Barbara Bradler, R. T.
Director of Radiology
12300 McCracker Road
Garfield Heights, Ohio 44125

License No. 34-05382-01

30-2741

Gentlemen:

This refers to the routine safety inspection conducted by J. W. Patterson of this office on June 21, 1989, of activities authorized by NRC Byproduct Material License No. 34-05382-01 and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Norman L. McElroy
Norman L. McElroy, Chief
Nuclear Materials Safety
Section 1

Enclosure: Notice of Violation

cc w/enclosure:
DCD/DCB (RIDS)

RIII
Patterson/sv
7/3/89

RIII
McElroy
105

8907110109 890708
REG3 LIC30
34-05382-01 PDC

IE07
1/1