



Southern California Edison Company

P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

F. R. NANDY
MANAGER OF NUCLEAR LICENSING

August 9, 1989

TELEPHONE
(818) 302-1896

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Gentlemen:

Subject: Docket Nos. 50-361 and 50-362
Follow-up Report, Inoperable Fire Doors -- July 1989
San Onofre Nuclear Generating Station, Units 2 & 3

89 AUG 14 P2:01
RECEIVED
MRS
REGION V

The purpose of this letter is to provide a follow-up report for Technical Specification fire-rated assemblies (specifically fire doors) found inoperable during routine surveillances in July 1989. This monthly report and previous monthly reports provide updated information associated with the initial 1983 report.

The attachment to this letter identifies fire doors found inoperable during the July routine surveillances and consists of: 9 latching mechanism failures and 2 closure mechanism failures. As each of these deficiencies was identified, compensatory fire watches were established pursuant to Technical Specification 3.7.9, Action Statement "a". No doors were found to be blocked open in July.

If you require any additional information, please advise.

Very truly yours,

Enclosure

cc: C. Caldwell (USNRC Senior Resident Inspector, Units 1, 2 and 3)
U. S. Nuclear Regulatory Commission Document Control Desk
Institute of Nuclear Power Operations (INPO)

8908280267 890809
PDR ADOCK 05000361
S PNU

11
IE-27

ATTACHMENT
SOUTHERN CALIFORNIA EDISON COMPANY
INOPERABLE FIRE DOORS FOR THE MONTH OF JULY 1989
SAN ONOFRE NUCLEAR GENERATING STATION
UNITS 2 AND 3, DOCKET NOS. 50-361 and 50-362

I. Latching Mechanism Failures:

Number of doors inoperable - 9, as follows:

<u>Door Number</u>	<u>Inoperable</u>	<u>Operable</u>
AC-121	06/20/89	07/03/89
AC-105	06/22/89	- - -
AC-428	06/27/89	- - -
C2-406	06/30/89	07/31/89
AC-221	07/05/89	07/25/89
AC-223	07/06/89	07/25/89
FH2-101	07/22/89	- - -
FH3-103	07/22/89	- - -
FH3-404	07/25/89	- - -

II. Closure Mechanism Failures:

Number of doors inoperable - 2, as follows:

<u>Door Number</u>	<u>Inoperable</u>	<u>Operable</u>
AC-119	04/30/89	- - -
AC-221	07/05/89	07/25/89

III. Doors Blocked Open:

Number of doors blocked open - None

fdr.jul/1