## BOSTON COLLEGE CHESTNUT HILL, MASSACHUSETTS 02167-3811

DEPARTMENT OF PHYSICS (617) 552-3575 Docket No. 030-17140 License No. 20-00642-07 March 7, 1989

Mr. John S. Kinneman, Chief Nuclear Materials Safety Section B Division of Radiation Safety and Safeguards Nuclear Regulatory Commission Region I 475 Allendale Road King of Prussia, Pennsylvania 19406

Dear Mr. Kinneman:

This is in response to your letter of February 14, 1989 which reports on the inspection of our facility by Mr. C. T. Oberg on December 15 and 16, 1988.

We regret that we have been found not in full compliance with NRC requirements in several areas. We have initiated the steps outlined below to correct the violations cited in your letter.

Item A.1 We have made arrangements to have all our survey instruments calibrated immediately. In addition we have (a) requested that Mr. N. J. Magliano, University Environmental Safety Engineer, assume responsibility for keeping track of the dates when calibrations are carried out and to alert users when recalibrations are due; (b) Mr. Magliano has further been requested to establish that the calibrations have indeed been carried out in a timely fashion; (c) We have requested that the University purchase additional monitoring instruments so that users will have instruments available to them during the time their instruments are out to be calibrated.

Item A.2 We have reminded all users of byproduct materials of the University regulation forbidding the consumption or storage of foodstuffs in areas where these materials are employed. We have asked the departmental representatives on the Radiation Safety Committee to be more vigilant monitoring their laboratories for this and other violations. We have asked the Radiation Safety Technician to be especially watchful with regard to this matter on her monthly survey rounds.

Item A.3 While the survey procedure cited in this part has always been conducted as part of the routine examination of incoming radioactive materials, there was no place for entering the results on the survey report sheet. The sheet has since been modified to include these items. A copy of the modified document is enclosed herein.

Item B. We have arranged to conduct an immediate survey of the sources in question and have established a calendar to be kept by the Radiation Safety Officer with a copy to be kept by the Chairman of the Radiation Safety Committee alerting the RSO of the due dates for resurvey.

Item C. The events consequent to this particular oversight seem to be adequate encouragement to avoid ever again failing to record such surveys.

Item D. The labeling of this storage area has been a problem caused by the attachment undergraduates seem to have for the signs which we fasten to the entrances of those areas. Since the room in question has no window in the door, we fasten the signs to the outside of the door by the best means available. Currently, the signs are constructed of aluminum and are both glued and screwed to the door. We have requested of the radiation safety technician that she include checking the door as part of her monthly duties.

Item E. Form NRC-3 and a notice of the content and location of the cited documents have been posted in every area in which byproduct materials are stored or utilized.

We anticipate that all the above procedures will be completed and we shall be in complete compliance on all items no later than 10 April 1989.

I trust this will constitute a satisfactory resolution to these matters. Should you have any questions or require any alteration of the procedures described herein, please contact me directly.

Very truly yours,

Prof. George J. Goldsmith

Radiation Safety Officer

## RADIOISOTOPE SHIPMENT RECEIPT REPORT

1. PO#_		Survey Date:/ Time:
Supplie	Amersham:Other:	Surveyer(PRINT)
2. COND	ITION OF PACKAGE: Good	Crushed Punctured Other (specify)
3. CONTI		
	Chemical Form:	
	Quantity:	(mCi)
	Do vial contents and If no, specify nature	package slip agree? Yes No of difference:
4. TEST R	ESULTS:	
a) Test	Type: Wipe	Survey Meter
b) Outer	Container: Wipe Source Container: Wipe	CPM
5. PACKAO	GE DELIVERED TO: D	Dept. of
6. IF NRC/	CARRIER NOTIFICAT	TON IS REQUIRED, GIVE
Date:	J Time:	Person Notified:
. SIGNAT	URE OF SURVEYER:	

CONVERSATION	RECORD	1155 an	3/30/89
TYPE VISIT	CONFERENCE	TELEPHONE	ROUTING
Location of Visit/Conference:		) or	TOMING NAME/SYMBOL IN
with you Prof. George J. Goldsmith, &	250 etc.) Boston Co	dept., bureau, FELEPHO Nege 617-	NE NO. 552
SUBJECT	Chestrud Hill,	MA 185.	35
	ponse to NOV		
SIMMODY .	P88-001	20-00642	-0/
Summary Advised the RSO of	last the version	se to NOV IT	en Croas not
adeques and shows	Il de la	more speces	ue. Dequeste
That he review Here into	on and RI we	Deall lat	infor the
Tes ponse.			
At - 1:50 pm, Call	It the RSO ag	ain. Stated	he has Stafted
a he part procedure that	will provide &	xplicit i	ishuctions to
persons conducting radiation su	veys as fallows;		
1. A complete record of the			include; purpose
The survey; building room and	specific area (s)	in the room; in	strument used
or the survey and most record calibra			
nd with enough additional commer	its as necessary to n		
inder Tanbable. The formers) are	to be distributed in	sufficient que	entity for Distribution
es ordlined in Item 2.		10	10
2. Distribution; RSO, Cl	m of RSC, personts	) requesting the see	enery (5) and felo
(Radiation Safety file drawer)			D. A.A.
2	equired wholks or not the		/\
This under turbio	willle notes a	in NRC Thats	Loy letter
NAME OF PERSON DOCUMENTING CONVERSATION	SIGNATURE		DATE
	1 Can	9	3(30)89
ACTION TAKEN		1	
SIGNATURE	TITLE		DATE
			DATE
50271-101 20 U.S. G.P.O. 1963-381:526/6	CONVERSATION RECO	ORD	OPTIONAL FORM 271 (12-7