DMB

110

JE07

AUG 2 5 1989

License No. 12-10906-01

Precision Well Perforating Corporation ATTN: Mr. Greg Buchanan Outer West Ninth Street P. O. Box 484 Mt. Carmel, IL 62863

Gentlemen:

This refers to the routine safety inspection attempted by Mr. D. R. Gibbons of this office on August 1, 1989, of activities authorized by NRC Byproduct Material License No. 12-10906-01 and to the discussion of our findings with you at the conclusion of the inspection.

The inspector was informed that since the last inspection conducted in August 1984 licensed activity had been conducted in Illinois under License No. IL 12-10906-01. The inspector, also, confirmed that you had submitted a Form NRC-314 Disposition of Licensed Material to the Region III Office on July 19, 1989 requesting that the NRC License be terminated.

The inspector left a Form NRC-241 and explained the requirement to submit the form to the Region III Office prior to performing licensed activities in non-Agreement States.

No violations of NRC requirements were identified during this attempt to inspect your licensed activities.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. J. Sreniawski, Chief Nuclear Materials Safety Section 1

cc: DCD/DCB (RIDS)

9010333 890825 3 LIC30

RIII (HREX) Gibbons/ib

RIII Srenjan