AUG 2 1 1989

In Reply Refer To: Docket: 50-458/89-30

Gulf States Utilities

ATTN: Mr. James C. Deddens

Senior Vice President (RBNG)

P.D. Box 220

St. Francisville, Louisiana 70775

Gentlemen:

This refers to the inspection conducted by Mr. J. Kelly of this office during the period June 19-23, 1989, of activities authorized by NRC Operating License NPF-47 for River Bend Station, and to the discussion of our findings with you and members of your staff at the conclusion of the inspection.

The inspection covered certain areas of your physical security program. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspector. The areas inspected and the inspection findings are documented in the enclosed inspection report.

During this inspection, it was found that one of your activities was in violation of NRC requirements. This violation occurred when a security officer serving a compensatory post of access control at a vital area barrier portal became inattentive. Although the Enforcement Policy allows for discretion on citing this type of licensee identified and reported violation, this violation is being cited because it directly resulted from supervision's denial of a valid request for relief from the security officer. Consequently, you are required to respond to this violation, in writing, in accordance with the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Your response should be based on the specifics contained in the Notice of Violation enclosed with this letter.

We are also concerned about the firearms qualification certification process for the security staff. The inspector could not ascertain from records which security officer firing attempts were for qualification certification and which were for practice. Consequently, this is an unresolved item, and you are requested to respond, in writing, to this concern within 30 days of the receipt of this letter. This concern is discussed in paragraph 4 of the enclosed inspection report.

We have also examined actions you have taken with respect to previously identified inspection findings. The status of these items is identified in paragraph 2 of the enclosed report.

RIV: SEPSOP JKelly 9901 8/17/89801 C:SEPS:RPB DPowers AP 8/17/89 C: RPB alp BMurray yar 8/17/89 15RS 9

DEDRP W JLMilhoar 8/21/89

8909050032 890821 PDR ADOCK 05000458 Q PNU IEO4

The material enclosed herewith contains Safeguards Information as defined by $10\ \text{CFR}$ Part 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material, with the exception of the report cover page which is an inspection summary, will not be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

James L. Milham, Director Division of Reactor Projects

Enclosures:

 Appendix A - Notice of Violation
 Appendix B - NRC Inspection Report 50-458/89-30

cc w/summary page only: Gulf States Utilities ATTN: J. E. Booker, Manager River Bend Oversight P.O. Box 2951 Beaumont, Texas 77704

Gulf States Utilities
ATTN: Les England, Director
Nuclear Licensing - RBNG
P.O. Box 220
St. Francisville, Louisiana 70775

Louisiana State University, Government Documents Department

Louisiana Radiation Control Program Director

bcc copy of entire report:
RIV Security File
P. A. Starcher, RSGB/NRR
R. D. Martin, RA
B. Beach, DRSS
Chief, RPB
Section Chief, SEPS:RPB

Security Inspector Resident Inspector SEPS:RPB File G. F. Sanborn, EU D. M. Crutchfield, NRR bcc copy of letter and inspection summary only w/766:
DRP RIV Files
Lisa Shea, RM/ALF RSTS Operator
MIS Section Chief, DRP/C
Project Engineer, DRP/C

bcc copy of letter and inspection summary only w/out 766: DMB IE-04
DRS
R. Paulson, NRR Project Manager