



The National **Pharmaceutical** Service Network

March 31, 1987

Materials Licensing Section U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

> RE: Control #30042 License #13-19451-01MD

Gentlemen,

Please make the following change in our license application for renewal of MRC License No. 13-19451-01MD. We wish to modify the physical layout of the laboratory by adding swinging bar-type doors between restricted and unrestricted areas and omit the door between dispensing area and hallway. These changes will in no way compromise the security of licensed material.

Attached is a new page 6 for Item 9. Please use this to replace the present page in the application submitted on 10/15/85.

Your consideration in this matter is appreciated.

Sincerely,

R. Kent Edward

Health Physics Group

Syncor International Corporation

Enclosure

cc: Frank Comer

Carmen Czerwinski Larry Adamovic

Syncor International Corporation Medical Services Group 1010 West Jackson Boulevard Chicago, Illinois 60607 (312) 666-8200

8903200576 880429 REG3 LIC30 13-19451-01MD PNU RECEIVED

APR 02 1987

APR 2 1987

REGION III

Date: 10/15/85

Dyer, Indiana

