



Log # TXX-89664
File # 10110
903.9
Ref. # 10CFR50.55(e)

August 31, 1989

William J. Cahill, Jr.
Executive Vice President

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
IMPROPER APPLICATION OF CONSTRUCTION AIDS
SDAR: CP-87-59 (SUPPLEMENTAL REPORT)


Gentlemen:

On September 21, 1987, TU Electric notified the NRC via report logged TXX-6750 of a reportable deficiency involving the improper application of construction aids. The latest report on this issue, logged TXX-89164, was submitted March 29, 1989. This supplemental report is submitted to update the corrective action schedule.

The implementation of the corrective actions (replacement of the T-IW and T-IIW cable tray fittings) for Unit 1 has been rescheduled to be completed prior to fuel load. The schedule for Unit 2 remains unchanged.

Sincerely,

William J. Cahill, Jr.

By: 
D. R. Woodlan
Docket Licensing Manager

SEC/smp

c - Mr. R. D. Martin, Region IV
Resident Inspectors, CPSES (3)

8909060261 890831
FDR ADOCK 05000445
S FDC

IE27
1/0