

DUKE POWER COMPANY  
P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

August 30, 1989


Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Subject: Catawba Nuclear Station, Unit 2  
Docket No. 50-414  
End of Cycle 2 Inservice Inspection Report

Gentlemen:

Pursuant to 10 CFR 50.55 (a) (q) and Catawba Nuclear Station Technical Specification 4.0.5, please find attached the Catawba Unit 2 end-of-cycle 2 Inservice Inspection Report. The Unit 2 end-of-cycle 2 refueling outage ended on June 9, 1989. This Inservice Inspection was performed in accordance with Section XI of the ASME Boiler and Pressure Vessel Code and applicable addenda.

Very truly yours,



H. B. Tucker

Attachment

JGT/4/U2C2ISI

xc: Mr. S. D. Ebnetter, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Mr. W. T. Orders  
NRC Resident Inspector  
Catawba Nuclear Station

A047  
1/1