

JUL 7 1989

In Reply Refer To:
License: 35-07464-03
Docket: 030-02898

Oklahoma Medical Research Foundation
ATTN: Dr. Reagan H. Bradford
825 NE 13th Street
Oklahoma City, Oklahoma 73104

Dear Dr. Bradford:

This refers to the routine, unannounced radiation safety inspection conducted by Messrs. G. M. Vasquez and W. L. Holley of this office on June 14, 1989, of activities authorized by NRC Byproduct Material License 35-07464-03 and to the discussion of our findings with Dr. D. Ahluwalia at the conclusion of the inspection.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, and observations by the NRC inspectors.

No violations or deviations were identified.

Should you have any questions about this inspection, we will be pleased to discuss them with you.

Sincerely,
Original Signed By

William L. Fisher, Chief
Nuclear Materials Safety Branch

cc:
Oklahoma Radiation Control Program Director

bcc:
JMB - Original (IE-07)
RDMartin
ABBeach
WLFisher
LShea, RM/ALF (AR-2015)
*CLCain
*DAPowers
*Inspector
*NMSB
*MIS System
*RIV Files (2)
*RSTS Operator

*W/766

RIV:NMIS *nmw*
GMVasquez:cd
7/6/89

8907190214 890707
REG4 LIC30
35-07464-03 PDC

C:NMIS *nmw*
CLCain
7/7/89

C:NMSB *nmw*
WLFisher
7/7/89

IE-07
110