


UNC MINING AND MILLING

3/3

*its return
to Kinross*

Report #64




Division of United Nuclear Corporation
A **UNC RESOURCES** Company

Church Rock Operations
P.O. Drawer QQ

Gallup, New Mexico 87301
Telephone 505/722 6651

March 4, 1982



Mr. Kent Breese, P.E.
Environmental Engineer
Uranium Licensing Section
New Mexico Environmental Improvement Division
P. O. Box 968
Santa Fe, New Mexico 87504-0968

Dear Mr. Breese:

Pursuant to our telephone conversation on February 25, 1982,
please find enclosed two revised copies of the Tailings Structure
Failure Contingency Plan.

Should the plan be acceptable to your agency, then it will be in-
corporated into Appendix C.1 of the Environmental Report which
UNC submitted with the NECR Mill License renewal.

In addition, two copies of corrections to the MILDOS are also
enclosed.

If you have any questions please feel free to contact me.

Sincerely,

H. John Abbiss, P.E.
Vice President
Environmental & Safety Services

HJA/sp

Enclosure

cc: T. Bailey
S. Crout
A. Kuhn

9804200431 820304
PDR ADOCK 04008907
C PDR