

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

MAR 2 2 1989

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Donald C. Shelton,
Vice President
Nuclear

Edison Plaza 300 Madison Avenue Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. P. M. Byron, J. S. Stewart, E. R. Schweibinz, J. Ulie, and D. C. Kosloff of this office and others on January 16 through February 28, 1989, of activities at Davis-Besse Nuclear Power Station authorized by Facility Operating License No. NPF-3 and to the discussion of our findings with Mr. L. Storz at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as described in the enclosed Appendix.

With respect to item 2 the inspection showed that action had been taken to correct the identified violation and to prevent recurrence. Our understanding of your corrective actions are described in Paragraph 2.g. of the enclosed inspection report. Consequently, no reply to this violation is required and we have no further questions regarding this matter at this time.

Regarding item 1, a written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

TEO1

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

for R. C. Knop, Chief
Reactor Projects Branch 3

Enclosures:

1. Notice of Violation

2. Inspection Report No. 50-346/89005(DRP)

cc w/enclosures:
L. Storz, Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch
Resident Inspector, RIII
Harold W. Kohn, Ohio EPA
James W. Harris, State of Ohio
Robert M. Quillin, Ohio
Department of Health
State of Ohio, Public
Utilities Commission