



**Boston Edison**

Pilgrim Nuclear Power Station  
Rocky Hill Road  
Plymouth, Massachusetts 02360

**L. J. Olivier**

Vice President Nuclear Operations  
and Station Director

April 30, 1998

BECO Ltr. 2.98.056

U.S. Nuclear Regulatory Commission  
Attn.: Document Control Desk  
Washington, D.C. 20555

Docket No. 50-293  
License No. DPR-35

The enclosed Licensee Event Report (LER) 98-005-00, "Supports For RHR Quadrant Coolers Were Found Not To Be Seismically Qualified," is submitted in accordance with 10 CFR Part 50.73.

This letter contains the following commitment:

- Permanent modifications will be made to restore VAC 204A, B, C and D to full qualification design basis seismic capability before startup from RFO 12.

Please do not hesitate to contact me if there are any questions regarding this report.

*W Desmond for*  
L. J. Olivier *Jack Alexander*  
*per telecom*

*Lezz*

KRD/JRH  
ler/9800500  
Enclosure: LER 98-005-00

9805060025 980430  
PDR ADOCK 05000293  
S PDR

Boston Edison Company

cc: Mr. Hubert J. Miller  
Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Sr. NRC Resident Inspector - Pilgrim Station

INPO Records  
700 Galleria Parkway  
Atlanta, GA 30339-5957

Standard BECo LER Distribution