

SEP 05 1989

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Donald Shelton
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. T. Ploski and J. Foster of this office on August 7-11, 1989, of activities at Davis-Besse Nuclear Power Station, authorized by Facility Operating License No. NPF-3, and to the discussion of our findings with you and members of your staff at the conclusion of the inspection.


The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosures, will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



L. Robert Greger, Chief
Reactor Programs Branch

Enclosure: Inspection Report
No. 50-346/89018(DRSS)

See Attached Distribution

RIII
Ploski/kja
YES

RIII
Foster
/m

yes
RIII
wbs
Shelton
9/1/89

yes
RIII
RWD
DeFayette
9/1/89

RIII
Greger
9/5/89

IE35
/1

Toledo Edison Company

2 SEP 05 1989

Distribution

cc w/enclosure:

L. Storz, Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

James W. Harris, State of Ohio

Roger Suppes, Ohio

Department of Health

A. Grandjean, State of Ohio,

Public Utilities Commission

D. Bement, FEMA, Region V

W. Travers, EPB, NRR