



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

MAY 16 1989

Docket No. 50-341

EA 89-106

The Detroit Edison Company
ATTN: B. Ralph Sylvia
Senior Vice President
Nuclear Operations
6400 North Dixie Highway
Newport, MI 48166

Gentlemen:

This confirms our plans as discussed on May 15, 1989, between P. Pelke of my staff and L. Goodman of your staff to conduct an Enforcement Conference at 8:30 a.m. (CDT) on May 26, 1989, at the Region III Office in Glen Ellyn, IL. The Enforcement Conference is to discuss the apparent violations documented in Inspection Report 50-341/89006(DRP) regarding failure to properly design the rail car door seals for flood protection and secondary containment integrity requirements.

We will gladly discuss any questions you may have regarding this matter.

Sincerely,

William L. Stoney
Edward G. Greenman, Director
Division of Reactor Projects

cc: Patricia Anthony, Licensing
P. A. Marquardt, Corporate
Legal Department
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
Harry H. Voight, Esq.
Michigan Department of
Public Health
Monroe County Office of
Civil Preparedness
J. Lieberman, OE
L. J. Chandler, OGC

TEAS
1/0