

Official

SEP 01 1989

Docket No. 70-1151
License No. SNM-1107

Westinghouse Electric Corporation
ATTN: Mr. E. P. Loch, Manager
Columbia Plant
Commercial Nuclear Fuel Division
Drawer R
Columbia, SC 29250

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 70-1151/89-06

This refers to the Nuclear Regulatory Commission (NRC) Operational Safety Assessment conducted by G. L. Troup and other members of the team on July 31 - August 4, 1989. The inspection included a review of activities authorized for your Columbia facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified. Two items were identified which should be addressed in your license renewal application.

In accordance with 10 CFR 2.790(a), a copy of this letter and enclosures, and any reply will be placed in the NRC Public Document Room. If you wish to withhold information contained therein, please notify this office by telephone within ten days of the date of this letter and submit a written application to withhold information contained therein promptly thereafter. Such application must be consistent with the requirement of 10 CFR 2.790(b)(1). If we do not hear from you in this regard within the period specified above, this letter and enclosures, and any reply will be made available to the public and be placed in the NRC Public Document Room.

8909190278 890901
PDR ADOCK 07001151
C FDC

11
2E07

SEP 01 1989

Should you have any questions concerning this letter, please contact us.

Sincerely,

**ORIGINAL SIGNED
BY**

W. E. CLINE

William E. Cline, Chief
Nuclear Materials Safety and
Safeguards Branch
Division of Radiation Safety
and Safeguards

Enclosure:
NRC Inspection Report

cc w/encl:
State of South Carolina

bcc w/encl:
G. Sjoblom, NMSS
L. Rouse, ICUF/NMSS
Document Control Desk
bcc w/o encl:
License Fee Management Branch

R11:DRSS
GTrouper
09/1/89

R11:DRSS
EMcAlpine
09/1/89