Docket No. 50-409

Dairyland Power Cooperative ATTN: Mr. J. W. Taylor General Manager 2615 East Avenue - South LaCrosse, WI 54601

Gentlemen:

This refers to the routine inspection conducted by Mr. D. E. Miller of this office on May 8-11, 1989, of activities at LaCrosse Boiling Water Reactor authorized by NRC Operating License No. DPR-45 and to the discussion of our findings with Mr. Parkyn at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

8906010285 890525 PDR ADDCK 05000409 Q PNU

L. Robert Greger, Chief Reactor Programs Branch

Enclosure: Inspection Report No. 50-409/89001(DRSS)

See Attached Distribution

Miller/jaw

Schumacher

46

FIII Flackiw s/c4

RIII Greger 5/25 12 Ege /

Distribution

cc w/enclosure:
J. Parkyn, Plant Superintendent
DCD/DCB (RIDS)
Licensing Fee Management Branch
Peter B. Erickson, LPM/NRR
Virgil Kanable, Chief
Boiler Section
Charles Thompson, Chairman
Wisconsin Public Service
Commission
Spark Burmaster, Coulee
Region Energy Coalition
R. I. Braund (SLO),
Wi Div. of Emergency Government
Lawrence J. McDonnell, Chief
Radiation Protection Section
WI Department of Health and
Social Services, Division
of Health