Docket No. 50-267

Mr. R. O. Williams, Jr. Senior Vice President, Nuclear Operations Public Service Company of Colorado Post Office Box 840 Denver, Colorado 80201-0840

Dear Mr. Williams:

SUBJECT: SAFETY EVALUATION ON LER 87-20 - INTERACTIONS OF FORT ST. VRAIN PLANT PROTECTIVE SYSTEM AND STEAMLINE RUPTURE DETECTION/ISOLATION SYSTEM WITH CONTROL SYSTEMS (TAC NO. 69264)

We have reviewed your submittals dated November 22, 1988 and April 7, 1989 concerning interactions between the steamline rupture detection/isolation system (SLRDIS), the plant protective system (PPS) and the control system at Fort St. Vrain. Your letters were in response to our requests for additional information dated September 20, 1988 and January 12, 1989.

We have enclosed our safety evaluation on this subject. Our concerns about potentially undesirable interactions between SLRDIS, PPS and the control system for certain control valves are resolved.

Sincerely,

/s/ Kenneth L. Heitner, Project Manager Project Directorate - IV Division of Reactor Projects - III, IV, V and Special Projects Office of Nuclear Reactor Regulation

Enclosure: As stated

cc w/enclosure: See next page

DISTRIBUTION

Docket File G. Holahan P. Nocnan B. Grimes NRC PDR L. Rubenstein Project Manager S. Newberry Local PDR J. Calvo OGC-Rockville ACRS (10) PD4 Reading F. Hebdon E. Jordan PD4 Plant File

DOCUMENT NAME: FSV 8955

PD4/LA JA PD4/PM RH PNoonan KHeitner:bj 05/3/89 05/23/89 B906070174 B90526 PDR ADOCK 05000267 PNU

SICB/0 SNewberry 05/25/89

DFOI



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

May 26, 1989

Docket No. 50-267

Mr. R. O. Williams, Jr. Senior Vice President, Nuclear Operations Public Service Company of Colorado Post Office Box 840 Denver, Colorado 80201-0840

Dear Mr. Williams:

SUBJECT: SAFETY EVALUATION ON LER 87-20 - INTERACTIONS OF FORT ST. VRAIN PLANT PROTECTIVE SYSTEM AND STEAMLINE RUPTURE DETECTION/ISOLATION SYSTEM WITH CONTROL SYSTEMS (TAC NO. 69264)

We have reviewed your submittals dated November 22, 1988 and April 7, 1989 concerning interactions between the steamline rupture detection/isolation system (SLRDIS), the plant protective system (PPS) and the control system at Fort St. Vrain. Your letters were in response to our recuests for additional information dated September 20, 1988 and January 12, 1989.

We have enclosed our safety evaluation on this subject. Our concerns about potentially undesirable interactions between SLRDIS, PPS and the control system for certain control valves are resolved.

Sincerely,

Dimmette I. Heitz

Kenneth L. Heitner, Project Manager Project Directorate - IV Division of Reactor Projects - III, IV, V and Special Projects Office of Nuclear Reactor Regulation

Enclosure: As stated

cc w/enclosure: See next page Mr. R. O. Williams, Jr. Public Service Company of Colorado

:20

Mr. D. W. Warembourg, Manager Nuclear Engineering Division Public Service Company of Colorado P. O. Box 840 Denver, Colorado 80201-0840

Mr. David Alberstein, Manager Fort St. Vrain Services GA International Services Corporation Post Office Box 85608 San Diego, California 92138

Mr. H. L. Brey, Manager Nuclear Licensing and Resource Management Division Public Service Company of Colorado P. O. Box 840 Denver, Colorado 80201-0840

Senior Resident Inspector U.S. Nuclear Regulatory Commission P. O. Box 640 Platteville, Colorado 80651

Kelley, Standfield & O'Donnell ATTN: Mr. J. K. Tarpey Public Service Company Building Room 900 550 15th Street Denver, Colorado 80202

Regional Administrator, Region IV U.S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Chairman, Board of County Commissioners of Weld County, Colorado Greeley, Colorado 80531

Regional Representative Radiation Programs Environmental Protection Agency 1 Denver Place 999 18th Street, Suite 1300 Denver, Colorado 80202-2413 Fort St. Vrain

Albert J. Hazle, Director Radiation Control Division Department of Health 4210 East 11th Avenue Denver, Colorado 80220

Mr. Charles H. Fuller Manager, Nuclear Production and Station Manager Public Service Company of Colorado 16805 Weld County Road 19-1/2 Platteville, Colorado 80651

Mr. P. F. Tomlinson, Manager Quality Assurance Division Public Service Company of Colorado 16805 Weld County Road 19-1/2 Platteville, Colorado 80651

Mr. D. D. Hock President and Chief Executive Officer Public Service Company of Colorado Post Office Box 840 Denver, Colorado 80201-0840

Commitment Control Program Coordinator Public Service Company of Colorado 2420 W. 26th Ave. Suite 100-D Denver, Colorado 80211