

APR - 5 1989

Docket No. 030-12031

License No. 53-16991-01 MD
EA No. 89-45

Pacific Radiopharmacy Ltd.
347 North Kuakini Street
Honolulu, Hawaii 96817

Attention: Myron L. Tong, Chairman
Board of Directors

Gentlemen:

SUBJECT: NRC INSPECTION AND ENFORCEMENT CONFERENCE

This refers to the routine safety inspection conducted by James L. Montgomery of this office on January 4, 18, February 3, March 17, and 23, 1989 of activities authorized by NRC License No. 53-16991-01 MD and to the discussion of our findings held by Mr. Montgomery with Dr. Phan The Tran at the conclusion of the inspection.

The findings from this inspection were also discussed with you, Dr. Tran and your consultants from Mid-Pacific Medical Physics by Messrs. R. Scarano and R. Thomas, of this office, during an enforcement conference on March 9, 1989. Inspection Report No. 030-12031/89-02 is enclosed for your information. See Appendix B.

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Based on the results of this inspection, it appears that certain of your activities were not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation enclosed as Appendix A to this letter. These items have been categorized into severity levels as described in the NRC Enforcement Policy, 10 CFR Part 2, Appendix C (1988).

We have verified that adequate surveys of your outside waste storage area had been conducted as specified in your August 28, 1981 license application. However, we are concerned that the survey form used was inaccurate and misleading. You will be expected to resolve the survey discrepancies during the current license renewal process. Failure to correct these issues could result in future violations of NRC requirements.

8904140175 890405
REGS LIC30
53-16991-01MD PDC

TE07
11
~~11~~

APR - 5 1989

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional precautions planned to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

If you have any questions concerning this inspection or the enforcement conference, we will be glad to discuss them with you.

Sincerely,

original signed

Ross A. Scarano, Director
Division of Radiation Safety and
Safeguards

Enclosure:

Appendix A: Notice of Violation

Appendix B: Enforcement Conference (Report No. 03012031/8902)

bcc w/enclosure:

B. Faulkenberry

J. Martin

docket file

State of Hawaii

J. Zollicoffer

M. Smith

A. Johnson

REGION V/dot

JLMontgomery

3/30/89 *JLM*

A
AJohnson

4/3/89

RT
RThomas

3/29/89

RCR
RJPate

3/29/89

REQUEST COPY]	REQUEST COPY]	REQUEST COPY]	REQUEST COPY]
YES / NO]	YES / NO]	YES / NO]	YES / NO]

SEND TO PDR]
YES / NO]