

OCT -3 1989

In Reply Refer To:
Docket: 50-267/89-19

Public Service Company of Colorado
ATTN: A. Clegg Crawford, Vice President
Nuclear Operations
P.O. Box 840
Denver, Colorado 80201-0840

Gentlemen:

This refers to the inspection conducted by Messrs. R. C. Stewart and I. Barnes of this office during the period August 21-26 and 29-30, 1989, of activities authorized by NRC Operating License DPR-34 for Fort St. Vrain Nuclear Generating Station, and to the discussion of our findings with Mr. D. Scott and other members of your staff at the conclusion of the inspection.

Areas examined during the inspection included Region 19 control rod drive (CRD) assembly recovery activities, followup on Region 19 CRD clevis bolt failures, and review of steam generator ring header cracking problems. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspectors. The inspection findings are documented in the enclosed inspection report.

Within the scope of the inspection, no violations or deviations were identified.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Original Signed By:
Thomas P. Gwynn

James L. Milhoan, Director
Division of Reactor Projects

Enclosure:
Appendix - NRC Inspection Report
50-267/89-19 w/Attachments

cc w/enclosure:
Fort St. Vrain Nuclear Station
ATTN: C. Fuller, Manager, Nuclear
Production Division
16805 WCR 194
Platteville, Colorado 80651

RIV:RI:MQPS * C:MQPS *
RS Stewart/cjg IBarnes
/ /89 / /89

D:DRS * 80 10/2/89 D:DRP
LJCallan 10/2/89 JLMilhoan
/ /89 9/13/89
10

*previously concurred

8910120071 891003
FDR ADOCK 05000267
FDC

IE01
11

Public Service Company of
Colorado

-2-

Fort St. Vrain Nuclear Station
ATTN: P. Tomlinson, Manager
Quality Assurance Division
16805 WCR 19½
Platteville, Colorado 80651

Colorado Public Utilities Commission
ATTN: Ralph Teague, P.E.
1580 Logan Street OL1
Denver, Colorado 80203

Colorado Radiation Control Program Director

bcc to DMB (IE01)

bcc distrib. by RIV:

*RRI	*R. D. Martin, RA
*Section Chief (DRP/B)	*Project Engineer (DRP/B)
*RPB-DRSS	Lisa Shea, RM/ALF
*MIS System	*RSTS Operator
*K. Heitner, NRR Project Manager (MS: 13-D-18)	
*RIV File	*DRS
*DRP	
*I. Barnes	
*R. Stewart	

*w/766