



S Y S T E M S

5314 North Irwindale Avenue
Irwindale, California 91706 USA
Tel (626)960-3300 Fax (626)939-3870

March 11, 1998

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Subject: Addendum to our Reply of February 25, 1998
to a Notice of Violation, dated Jan 26, 1998

Reference: Docket No. 030-20431
License No. 04-23264-01

This is an addendum to our reply of February 25, 1998, as requested in a telephone conversation with Mr. David Skov on March 11, 1998.

NDC Systems has conducted a review of additional mislabeled devices containing radioactive sources that were discovered subsequent to the issuance of the NRC Confirmatory Order Modifying License dated January 13, 1997. NDC had previously communicated the discovery of these mislabeled devices to the NRC. NDC committed to provide a written report of NDC's review of this matter to the NRC.

The written report of the findings of our review was sent to NRC's Walnut Creek office in a letter dated January 29, 1998. A copy of that letter is attached and hereby submitted as an addendum to our reply to the Notice of Violation dated January 26, 1998.

Sincerely,

Yudie Fishman
President

Cc: U.S. Nuclear Regulatory Commission
Regional Administrator
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, Texas, 76011

U.S. Nuclear Regulatory Commission
Walnut Creek Field Office
1450 Maria Lane, Suite 300
Walnut Creek, CA 94596

IL2071

9803190145 980311
PDR ADOCK 03020431
C PDR

