



NO. OF NON EFFECTIVE WIRES → XX/XX
 TENDON DESIGNATION → XXXX
 NO. OF TIMES SURVEYED → XX
 DATE → DATE

NO. WIRE FAILURE SURVEY
 MOST CURRENT SURVEY
 V = VISUAL
 L = LIFT
 D = DETENSIONED
 ACCESSIBILITY
 V = VISUAL ONLY
 L = VISUAL AND LIFTOFF
 N = NOT ACCESSIBLE FOR VISUAL OR LIFTOFF

DRAWING GENERATED FOR TENDON SURVEILLANCE
 REPORT, MARCH 1985 - APPENDIX A
 JAMES H. M. SMITH
 CIVIL ENGINEER

IV-R V VI-L
 LAYER 2 BUTTRESSES IV - RIGHT & VI - LEFT

V-R VI
 LAYER 5 BUTTRESSES V - RIGHT & V - LEFT

VI-R I II-L
 LAYER 4 BUTTRESSES VI - RIGHT & II - LEFT

STONE & WEBSTER ENGINEERING CORPORATION		APPROVALS	
DRAWING NUMBER 13569.07-EC-1B		DATE	
Public LEGAL TENDON Service SURVEILLANCE Company PLAN of COLORADO SHEET 2		SCALE	
F.L. SI. YRAN		SCALE	

NO.	DATE	BY	REVISION

8504020156

PDR RIDS

8504020156

