

513-S3

UNIT 2

UNIT 3

UNIT 2 & 3

SERVICE EQUIP. NUMBER FIRE ZONE

NOTE 51
SEE ACD
52-3410

NOTE 52
SEE ACD
52-3315

NOTE 53
SEE ACD
52-MF39

SERVICE EQUIP. NUMBER FIRE ZONE

NOTE 54
SEE ACD
52-MF39

NOTE 55
SEE ACD
52-3059

NOTE 56
THE DIFFERENT
CABLE TYPES ARE
LISTED BELOW
P = POWER CABLE
PA = POWER ASSOCIATED
PM = POWER MAIN FEED
PR = POWER RES FEED
C = CONTROL

SERVICE EQUIP. NUMBER FIRE ZONE

NOTE 51-56

ROUTING OF ASSOCIATED CIRCUITS BY FIRE ZONE
DRESDEN NUCLEAR POWER STATION
UNIT 3
COMMONWEALTH EDISON CO.
CHICAGO, ILLINOIS

NUCLEAR SAFETY RELATED
EQUIPMENT IS SHOWN ON THIS DRAWING

SARGENT & LUNDY
ENGINEERS
CHICAGO

DRAWING NO.
ES-375

SHEET 12 K OF 1

RiDs

8205030132

