




NOTES:
1. LOOK FOR 42 INCHES BELOW & 42 INCHES ABOVE
2. LOOK FOR 42 INCHES BELOW & 42 INCHES ABOVE
3. LOOK FOR 42 INCHES BELOW & 42 INCHES ABOVE
4. LOOK FOR 42 INCHES BELOW & 42 INCHES ABOVE

LINE LISTING	PIPE SPEC.	DESIGN PRESS.	TEMPERATURE	CLASS	MATERIAL
01	101.4	45 PSI	200°F	P	CS
02	101.4	45 PSI	200°F	P	CS
03	101.4	45 PSI	200°F	P	CS
04	101.4	45 PSI	200°F	P	CS
05	101.4	45 PSI	200°F	P	CS
06	101.4	45 PSI	200°F	P	CS
07	101.4	45 PSI	200°F	P	CS
08	101.4	45 PSI	200°F	P	CS
09	101.4	45 PSI	200°F	P	CS
10	101.4	45 PSI	200°F	P	CS

SYSTEM CHANGE ORDER NUMBER CH-2574-2.1
REQUIRED FOR START-UP YES NO
DATE 11/2/78 BY 11/2/78
CHECKED BY 11/2/78 DATE 11/2/78
APPROVED BY 11/2/78 DATE 11/2/78

NUCLEAR SAFETY RELATED
DUKE POWER COMPANY
CATAWBA NUCLEAR STATION UNIT 2
FLOW DIAGRAM OF
LIQUID FLOW
SYSTEM (L.F.S.)
DWG. NO. 11.2.2-18

11.2.2-18

8107020244

