



CONTACT	POSITION FRONT VIEW			CWD
	CLOSE	NORM	OPEN	
1	X			*
2			X	*
3	X			
4			X	

SPRING RETURN TO NORM WITH KEY LOCK. KEY REMOVABLE IN NORM POS ONLY  
 \*-THIS SHEET

LIMIT SW DEVELOPMENT				
EBASCO SYMBOL	CONT.	VALVE OPMG. %	CWL	SH.
		0	100	
bo	1-2			*
bc	3-4			*
bc	5-6			*
ac	7-8			*
ao	9-10			*
bc	11-12			*
ao	13-14			*
bc	15-16			*
b %	17-18			*
b %	19-20			*
a %	21-22			*
b %	23-24			*
b %	25-26			*
a %	27-28			*
b %	29-30			*
a %	31-32			*
tc	35-36	OPENS ON OVERLOAD ON CLOSE STROKE		*
to	45-46	OPENS ON OVERLOAD ON OPEN STROKE		*

PROC APERTURE CARD

NUCLEAR SAFETY RELATED WPPSS QUALITY CLASS I

EBASCO SERVICES INCORPORATED DIV. CONTROL DR. P. GHATAK CH. E. OVALLE DATE SEP 30, 1977				APPROVED <i>H. Wallach</i> CH. PANELS		WASHINGTON PUBLIC POWER SUPPLY SYSTEM NUCLEAR PROJECTS NO. 3 & 5 CONTROL WIRING DIAGRAM RWST TO SI & CS PUMPS B ISO VA 2CH-VW401SRH (CH-530)		WPPS-3240 D-6001 SHEET 1956	
REV	DATE	BY	APPROVED						
1	12-8-81	RM	<i>[Signature]</i>						
2	5-29-80	W	<i>[Signature]</i>						

RIDS

8303040086

