



- \* THIS SHEET
- NOTES:
1. THIS IS A FLEXIBLE CABLE (12/C #12) WITH A MALE PLUG AT ONE END & CAN BE CONNECTED TO THE BURNDY FEMALE CONNECTOR AT EITHER TERMINAL BOX-(SA) OR-(SB)
  2. "BURNDY" 19 PIN ROUND CONNECTOR MOUNTED ON TERM BOX. PART SHOWN ON SH. 2006.
  3. FOR CHARGING PUMP CH-3 ONLY ONE CIRCUIT BREAKER IS PROVIDED, CONTACT IS SHOWN FOR REF ONLY.
  4. TS TRANSFER SWITCH DEVELOPMENT IS SHOWN ON SH. 2111 & 2112.

PRC  
APERTURE  
CARD

NUCLEAR SAFETY RELATED		WPPSS QUALITY CLASS I	
ERASCO SERVICES INCORPORATED DIV. CONTROL DR. S. GHATAK CH. E. OVALLE DATE SEP 30, 1977		WASHINGTON PUBLIC POWER SUPPLY SYSTEM NUCLEAR PROJECTS NO. 3 & 5 CONTROL WIRING DIAGRAM CHARGING P. MP 3 SEAL LUBE SYSTEM SH 1	
APPROVED: <i>[Signature]</i> APPROVED: <i>[Signature]</i>		WPPS-3240 D-6001 SHEET 2003	

REV.	DATE	BY	APPROVED
1	12-14-81	[Signature]	[Signature]
2	5-22-81	[Signature]	[Signature]
3	8-7-79	[Signature]	[Signature]
4	6-27-79	[Signature]	[Signature]

K&S 110 1000 11 74 400330

RIDS

8303040123

