



POSITION FRONT VIEW

CONTACT	STOP	NORM	START	CWD
1		X	X	*
2	X			
3	X	X		
4			X	*

SPRING RETURN TO NORMAL IN THIS SHEET

PRC APERTURE CARD

NUCLEAR SAFETY RELATED WFPB QUALITY CLASS III

BRASCO SERVICES INCORPORATED

WASHINGTON FIELD OFFICE

CONTROL ROOMS DIAGRAM

WFPB-3240 D-5001

RIDS

8303100303

