



ESSENTIAL COMPONENT
THIS ITEM IS OR CONTAINS A
SAFETY RELATED COMPONENT

GENERAL INFORMATION
 ASSY 1122066
 INSERT P801-67C
 PART OR GROUP NO.
 CONTROL ISSUE

- NOTES:
- FOR ITEMS 2 THRU 150 SEE ELECTRICAL DEVICE LIST 442406001, ITEM 1.
 - FOR ITEMS 1, 151 THRU 499 SEE INSERT PARTS LIST 1122066001.
 - FOR ITEMS 500 THRU 999 SEE HARDWARE LIST 442406001, ITEM 133.
 - FOR ITEMS 1000 AND UP SEE MARKING TABLE 1, THIS DRAWING. MARK PER PHOTO PROCESS SPEC 272A128, ITEM 136.
 - THIS INSERT IS PART OF P800 PANEL ASSY N13-P801
 - FOR WIRING INFORMATION SEE CONNECTION DIAGRAM 915E15-9 ITEM 162.
 - MARK REF DESIGNATIONS (REAR SIDE) ADJACENT TO DEVICES USING .12 HIGH CHARACTERS.
- ⚠ BOND MIMIC WITH ADHESIVE TAPE, ITEM 100. TRIM EXCESS TAPE.
 - ⚠ REF NOS (1), (2), (3), (4), (5), (6), (7), (8) & (9) ARE LINE NO'S PERTAINING TO MARKING SPEC.
 - ⚠ LENGTH AND ROUTING OF CONDUIT AND WIRING TO BE DETERMINED BY MFG AT ASSY
 - ⚠ ALL ELECTRICAL DEVICES ON THIS PANEL ARE DIV 2 UNLESS OTHERWISE SPECIFIED.
 - ⚠ CENTER MIMIC LINES ON DEVICES WHERE SHOWN CENTERED, OTHERWISE LOCATE APPROX AS SHOWN
 - ⚠ RESISTOR MOUNTING TO BE PER 195B355, ITEM 190, FOR SPACING AND STRAIN RELIEF.

APERTURE CARD

BALDWIN
 COPY # 100
 AUG 8 1981

FOR REFERENCE ONLY
 Not To Be Used For Construction

REV	DATE	BY	CHK'D	DESCRIPTION	QTY
1	1-31-80	L. BUCAN		CONTROL ISSUE	
2	1-31-80	L. BUCAN		CONTROL ISSUE	
3	1-31-80	L. BUCAN		CONTROL ISSUE	
4	1-31-80	L. BUCAN		CONTROL ISSUE	
5	1-31-80	L. BUCAN		CONTROL ISSUE	
6	1-31-80	L. BUCAN		CONTROL ISSUE	
7	1-31-80	L. BUCAN		CONTROL ISSUE	
8	1-31-80	L. BUCAN		CONTROL ISSUE	
9	1-31-80	L. BUCAN		CONTROL ISSUE	
10	1-31-80	L. BUCAN		CONTROL ISSUE	

(G) N13-P801-67C

RIDS

811120459

