



INFORMATION ONLY

SYMBOLS:
 --- Component on unit and all per 2-4 in main control room
 --- Component on 100V motor control center
 --- Component on remote control board 25-17
 --- Component on local health monitor (optional)

POWERHOUSE UNITS 1-3
 WIRING DIAGRAMS
 480V SHUTDOWN AUXILIARY PWR
 SCHEMATIC DIAGRAM
 BROWNS FERRY NUCLEAR PLANT
 TENNESSEE VALLEY AUTHORITY
 DIVISION OF SAFETY ENGINEERING
 SUBMITTED: [Signature] RECOMMENDED: [Signature] APPROVED: [Signature]
 KNOXVILLE 11-18-71 67 45N779-14 RA
 THIS DRAWING IS UNDER FUNCTIONAL CONFIGURATION CONTROL AS CONSTRUCTED

980130248

PHOTOGRAPHED
 IN KNOXVILLE

30X

PDR RIDS

8810130248

