

SUMMARY OF WRITTEN EXAM HANDOUTS TO APPLICANTS

SEABROOK INITIAL LICENSE EXAM

AUGUST 10, 2020

ADAMS package ML19105A186

Q3

OS1201.01, RCP Malfunction, Rev 19 – Attachment D graph of RCP Delta P vs Seal Leakoff

Q7

E-3, Steam Generator Tube Rupture, Rev 45 – Step 7 (page 7 of 56 only)

Q65

Technical Requirement 12 – Fire Detection Instrumentation, pages 2-12.1 thru 10, SSTR Rev 137

Q78

OS1213.02, Loss of RHR While Operating at Reduced Inventory or Mid-Loop Conditions, Rev 18. Page 5 of 44, page 40 thru 42 of 44

Q79

TK-002, Component Cooling Head Tanks CC-TK-19A&B Capacity vs Level Curve

Q80

ER 5.4, Page 7, Rev 38 – Figure 2, General Emergency Protective Action Flowchart