ES-401 Record of Rejected K/As Form ES-401-4

Facility: LaSalle County Station Date of Exam: 11/2/2020 to 11/13/2020

	,	Tier / Group	
partial or valid	295004 AA1.03	1/1	
ced with			
O – 4.1			
n partial e does	295019 AA1.02	1/1	
ced with			
O – 3.0			
by gas n 27.	261000 K3.01	2/1	
ced with			
O – 3.4			
Rod	201002 A4.06	2/2	
ced with			
O – 3.0			
	204000 K1.13	2/2	
ed with			
RO – 3.2			
ntrol - Could	2.4.34	3	
ced with			
	204000 K1.13	2/2	

3	2.4.35	RO (Q75) Knowledge of local auxiliary operator tasks during an emergency and
		the resultant operational effects. – Could not write a Tier 3 question for this KA.
		5/28/20 – FOLLOWING DISCUSSION WITH CHIEF EXAMINER : Replaced with 2.4.12
		2.4.12 Knowledge of general operating crew responsibilities during emergency operations. $RO-4.0 SRO-4.3$
2/1	262002 A2.01	SRO (Q89) Ability to (a) predict the impacts of the following on the uninterruptable power supply (AC/DC) and (b) based on those predictions, use procedures to correct, control, or mitigate the consequences of those abnormal conditions or operations: Undervoltage – Unable to write a valid SRO question for this KA.
		7/14/20 - FOLLOWING DISCUSSION WITH CHIEF EXAMINER : Replaced with 209001 A2.05
		209001 A2.05 Ability to (a) predict the impacts of the following on the LOW PRESSURE CORE SPRAY SYSTEM; and (b) based on those predictions, use procedures to correct, control, or mitigate the consequences of those abnormal conditions or operations: Core spray line break $RO-3.3$ $SRO-3.6$
2/2	226001 G2.4.46	SRO (Q92) Ability to verify that the alarms are consistent with the plant conditions. – Unable to write a valid SRO question for this KA.
		8/12/20 - FOLLOWING DISCUSSION WITH CHIEF EXAMINER : Replaced with 223001 G2.4.46
		223001 G2.4.46 Ability to verify that the alarms are consistent with the plant conditions. $RO-4.2$ SRO -4.2