NRC FORM 591M PART 1 (07-2012)*		U	S. NUCLEAR REGULATO	DRY COMMISSION
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
LICENSEE/LOCATION INSPECTED: Tri State Materials Testing Lab, LLC 60 Woodlawn Road Berlin, Connecticut 06037 REPORT NUMBER(S) 2019-001 3 DOCKET NUMBER(S) 4. LICENSE NUMBER(2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713 5. DATE(S) OF INSPECTION		
030-38513			July 17, 2019 –November 12, 2019	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X				
Statement of Corrective Actions				
I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.				
Title	Printed Name		Signature	Date
LICENSEE'S REPRESENTATIVE				THE COLUMN TO TH
NRC INSPECTOR	Craig Gordon, Sr. Health Ph	ysicist (laie)	Hdn_	11/12/19
BRANCH CHIEF	Chris Cahill, Chief, CIRDA B	Branch Mu	ll	11/2019
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013) G:\WBL Documents\WBL Inspection Records\R06-31462-01.2019-001.591M-Part1.doc				
SUNSI Review Completed By:	/RA / CGordon		X Public X	Non-Sensitive